

BULLETIN

NUMBER: RA-B-9-15-20

DATE: September 15, 2020

Rev: -

New FAA-PMA Molded Grease Seal



<u>Part Number</u>	<u>Replaces</u>	<u>List</u>
RA154-03000	Cleveland 154-03000	\$72.00

Model/Series Eligibility

Aerostar: PA-60-600 (Aerostar 600), PA-60-601 (Aerostar 601), PA-60-601P (Aerostar 601P), PA-60-700P (Aerostar 700P)

Bell: 230, 430

Diamond: DA 40

Maule: MXT-7-180

Navion: Navion A (L-17B), Navion B, Navion D, Navion E, Navion F, Navion G, Navion H

Pacific Aerospace Limited: 750XL

Piper Aircraft, Inc.: PA-23-160, PA-23-235, PA-23-250, PA-24-250, PA-24-260, PA-24-400, PA-28-140, PA-28-180, PA-28-181, PA-28-235, PA-28-236, PA-30, PA-31T, PA-31T2, PA-31T3, PA-31-300, PA-31-325, PA-31-350, PA-32-260, PA-32-300, PA-34-200, PA-34-200T, PA-34-220T, PA-38-112, PA-42, PA-42-720, PA-42-1000

Quest: Kodiak 100

Slingsby Aviation Ltd.: T67M260, T67M260-T3A

Textron Aviation Inc.: A36, A36TC, B36TC, E55, 58, B60, 58P, 58TC, 208, 208B, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 340, 340A, 402, 402A, 402B, 402C, 414A, 421, 421A, 421B, 421C, 425, 95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T-42), 95-C55, 95-C55A, D55, D55A, E55, E55A, 58, 58A with STC SA912GL installed, 340, 340A with STC SA281GL installed, 340, 340A with STC SA664GL installed, 401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414 with STC SA167GL installed, 401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C with STC SA197GL installed, 500, 500A, 500B, 500S, 500U, 560A, 560E with STC SA1457GL installed

Twin Commander: 560-F, 680, 680E, 680F, 680FL, 680FL(P), 680V, 680W, 681, 685, 690, 690A, 690B, 690C, 690D, 695, 695A, 695B, 720 with STC SA1458GL installed

Waco: YMF

RAPCO, inc.

REPLACEMENT AIRCRAFT PARTS CO.

445 Cardinal Lane, Hartland, WI, 53029

Phone: (262) 367-2292 Fax: (262) 367-7158

www.rapcoinc.com

