

BULLETIN

NUMBER: RA-B-10-1-17

DATE: Oct 1, 2017

Rev: -

New FAA-PMA Lead Harnesses



<u>Part Number</u>	<u>Replaces</u>	<u>List</u>
RA40531	McCauley 40531.....	93.33
RA40585	McCauley 40585.....	75.56

RA40531: Textron Aviation Inc. - 208, 208B with McCauley propeller 3GFR34C703/106GA-X

RA40585: Textron Aviation Inc. - C90A with McCauley propeller 4HFR34C768/94LMA-X
99, 99A, A99, A99A, B99, C99 with McCauley propeller
4HFR34C769/94LMA-X or 4HFR34C773/94LMA-X
B100 with McCauley propeller 5HFR34C1105/96LRB-X
B200, B200C (C-12F), B200C (C-12R), B200CT, B200T with
McCauley propeller 4HFR34C771/94LA-X
200, 200C, 200CT, 200T, A200C (UC-12B), A200CT (RC-
12D), A200CT (C 12D), A200CT (FWC-12D), B200,
B200C (C 12F), B200CT, B200T with McCauley propeller
5HFR34C1008/96LTA-0
208, 208B with McCauley propeller 4HFR34C775/96MGA-0
441 with McCauley propeller 4HFR34C661/90/LNA-X

RAPCO,inc.

REPLACEMENT AIRCRAFT PARTS CO.



445 Cardinal Lane, Hartland, WI, 53029

Phone: (262) 367-2292 Fax: (262) 367-7158

www.rapcoinc.com