

BULLETIN

NUMBER: RA-B-063018

DATE: June 30, 2018

Rev: -

New FAA-PMA Approved Shim Insulators



Part Number	Replaces	List
RA068-01700.....	Cleveland 068-01700	\$ 72.00
RA068-02700.....	Cleveland 068-02700	\$ 80.00
RA068-02900.....	Cleveland 068-02900	\$ 188.00

Rapco offers PMA approved replacement shim insulators. Reverse side illustrates the comprehensive installation eligibility. Please visit our website www.rapcoinc.com for more information.

RAPCO,inc.

REPLACEMENT AIRCRAFT PARTS CO.



445 Cardinal Lane, Hartland, WI, 53029

Phone: (262) 367-2292 Fax: (262) 367-7158

www.rapcoinc.com

Part	Aircraft	Models
RA068-01700	Aerostar	PA-60-600 (Aerostar 600), PA-60-601 (Aerostar 601), PA-60-601P (Aerostar 601P), PA-60-602P (Aerostar 602P), PA-60-700P (Aerostar 700P)
	B-N Group	BN2A MKIII, BN2A MKIII-2, BN2A MKIII-3
	Textron Aviation Inc.	D55, E55, 56TC, A56T, 58, T-34C (T-34C-1, 34C), 337E, T303
	Textron Aviation Inc.	35, 35R, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, 45 (TY-34), A45 (T 34A, B-45), D45 (T-34B), D55, D55A, E55, E55A, 95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, When STC SA19GL is installed.
RA068-02700	Textron Aviation Inc.	D55, D55A, E55, E55A, 95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, 58, 58A, 58P, 58TC, B60
	Textron Aviation Inc.	58P, 58TC, 60, A60, B60 When STC SA178GL, SA179GL is installed.
	Twin Commander	700
RA068-02900	Textron Aviation Inc.	425
	Textron Aviation Inc.	404 When STC SA781GL is installed.