

BULLETIN

NUMBER: RA-B-080516

DATE: August 5, 2016

Rev: B

New FAA-PMA Approved Shim Insulators



<u>Part Number</u>	<u>Replaces</u>	<u>List</u>
RA068-01100.....	Cleveland 068-01100	\$52.12
RA068-01600.....	Cleveland 068-01600	\$64.70
RA068-02800.....	Cleveland 068-02800.....	\$75.86
RA068-03100.....	Cleveland 068-03100.....	\$134.24
NEW! RA068-04100	Cleveland 068-04100	\$59.20
RA068-04600.....	Cleveland 068-04600	\$66.08

Rapco offers PMA approved replacement shim insulators. Reverse side illustrates the comprehensive installation eligibility. Please visit our website www.rapcoinc.com for more information.

RAPCO, inc.

REPLACEMENT AIRCRAFT PARTS CO.

445 Cardinal Lane, Hartland, WI, 53029

Phone: (262) 367-2292 Fax: (262) 367-7158

www.rapcoinc.com

Part Number	Aircraft	Eligibility:
RA068-01100	Allied Ag Cat Productions, Inc.	G-164
Replaces Cleveland 068-01100	American Champion (Bellanca) (Champion)	8GCBC
	B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN-2T-4R
	Cessna	210-5 (205), 336, 337B, LC40 -550FG, LC41 -550FG, LC42 -550FG, T303
	Cirrus Design Corporation	SR22
	Fletcher	FU-24, FU-24A
	Nomad TC Pty Ltd	N24A
	Pacific Aerospace Limited	FU24-954, FU24A-954
	Piper Aircraft, Inc.	PA-23-250, PA-24-400, PA-30, PA-32-260, PA -32-300, PA-32-301, PA-32-301T, PA -32R-300, PA-32RT-300, PA-32RT-300T, PA-34-200, PA-34-200T, PA-34-220T, PA-39, PA -44-180, PA-44-180T, PA-46-310P, PA -46-350P, PA-46-500TP
	Socata, S.A. Grumman	GA-7
	Vulcanair S.p.A.	P.68, P.68B, P.68C, P.68C-TC
	Air Tractor	AT-602
RA068-01600	Cessna	310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 335, 340, 340A, 401, 401A
Replaces Cleveland 068-01600	Cessna (STC SA54GL)	401B, 411, 411A, 414
	Cessna (STC SA110GL, SA111GL)	190, (LC-126A,B,C) 195, 195A, 195B, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F
	Piper Aircraft, Inc.	PA-31-300, PA-31-325, PA-31-350
	Thrush Aircraft, Inc. (Snow, Rockwell, Ayres)	S2R-T660
RA068-02800	Cessna	208, 208B
Replaces Cleveland 068-02800	Pacific Aerospace Limited	750XL
	Piper Aircraft, Inc.	PA-31-325, PA-31-350
	Quest	Kodiak 100
	Viking Air Limited (STC SA1402GL or Canadian STA SA90-1)	DHC-2 Mk. I, DHC-2 Mk.II, DHC-2 Mk.III
RA068-03100	Cessna	402, 402A, 402B, 402C, 414A, 421, 421A, 421B, 421C
Replaces Cleveland 068-03100	Cessna (STC SA167GL, SA281GL)	340, 340A, 401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414
	Cessna (STC SA197GL, SA664GL)	340, 340A, 401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C
	Piper Aircraft, Inc.	PA-31T, PA-31T1
	Piper Aircraft, Inc. (STC SA721GL)	PA-31-350
RA068-04100	Beechcraft	F90, 99, 99A,99A (FACH), A99A,B99, C99, 100,A100 (U-21F), B100,200, 200C, 200CT, 200T, A200 (C-12A),A200 (C-12C),A200C (UC-12B),A200CT (C-12D),A200CT (FWC-12D), A200CT (C-12F),A200CT (RC-12D),A200CT (RC-12G),A200CT (RC-12H),A200CT (RC-12K), A200CT (RC-12P),A200CT (RC-12Q),B200, B200C,B200C (C-12F),B200C (UC-12M), B200C (C-12R), B200C (UC-12F),B200CT, B200T,B200GT, B200CGT(When STC's SA646GL, SA650GL & SA890GL are installed.)
Replaces Cleveland 068-04100		
RA068-04600	Beechcraft (STC SA1222GL)	D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, RC-45J (SNB-5P), C-45H, TC -45H, TC-45J, JRB-6, 3N, 3NM, 3TM
Replaces Cleveland 068-04600	Viking Air Limited (Twin Otter) (STC SA1065GL)	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300